

Copyright

Notification of Difference from IAGSA Recommended Practice				
Name of Company:	NRG Exploration	CC/Skyhorse Avia	ition Pty Ltd	
Date submitted:	17/08/2023			
Which Recommended Practice or Safety Manual section is being deviated from?	Single pilot surveys - If so, does the Pilot have equipment operation duties in addition to those normally associated with flying the aircraft?			
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)
What is the reason for the deviation?	Our data acquisition and navigation system does require some minor input from the pilot which are in addition to the normal flying duties.			
Has a risk assessment been completed for the deviation?	Yes			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)	Procedure is noted in Operations Manual – "The PIC is only to operate the survey system when on the ground or in stable forward flight at a minimum altitude of 300 ft. above the highest obstacle"			
If No, what specific actions have been taken to provide for an equivalent level of safety?				
Name of Accountable Executive	Ryan Louw			
Signature of Accountable Executive				



Copyright

Notification of Difference from IAGSA Recommended Practice				
Name of Company:	NRG Exploration	NRG Exploration CC/Skyhorse Aviation Pty Ltd		
Date submitted:	17/08/2023			
Which Recommended Practice or Safety Manual section is being deviated from?	Flight and Duty Times - A maximum of 5 hours flight time on survey per day (excluding transit time)			
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)
What is the reason for the deviation?			re adhered to. Maximum nours for fixed wing oper	
Has a risk assessment been completed for the deviation?	No			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)	This restriction is always applied for BARS clients and when client or IAGSA procedures dictate and noted in the Risk Assessment as such. Flight and duty is monitored in both a predictive and reactive manner and therefore fatigue is closely managed.			
If No, what specific actions have been taken to provide for an equivalent level of safety?				
Name of Accountable Executive	Ryan Louw			
Signature of Accountable Executive				



Copyright

Notification of Difference from IAGSA Recommended Practice				
Name of Company:	NRG Exploration	NRG Exploration CC/Skyhorse Aviation Pty Ltd		
Date submitted:	17/08/2023			
Which Recommended Practice or			of 100 hours flight time i	n
Safety Manual section is being deviated from?	any consecutive	28 day period.		
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)
What is the reason for the deviation?		imes of regulator a secutive <b>30 day</b> per	re adhered to. SACAA re riod	egulations are 100
Has a risk assessment been completed for the deviation?	No			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)	This restriction is always applied for BARS clients and when client or IAGSA procedures dictate and noted in the Risk Assessment as such. Flight and duty is monitored in both a predictive and reactive manner and therefore fatigue is closely managed. Single pilot flight time extensions as per IAGSA recommendation is used when required.			
If No, what specific actions have been taken to provide for an equivalent level of safety?	·			
Name of Accountable Executive	Ryan Louw			
Signature of Accountable Executive				



Copyright

Notification of Difference from IAGSA Recommended Practice				
Name of Company:	NRG Exploration	NRG Exploration CC/Skyhorse Aviation Pty Ltd		
Date submitted:	17/08/2023			
Which Recommended Practice or Safety Manual section is being deviated from?	person essential		aircrew member required ding: a personal locator b	
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)
What is the reason for the deviation?	Alternate complia	ance procedure in p	lace	
Has a risk assessment been completed for the deviation?	No			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)	Survival kit in aircraft and grab bag with PELT. If required by risk assessment, items will be carried on person.			
If No, what specific actions have been taken to provide for an equivalent level of safety?				
Name of Accountable Executive	Ryan Louw			
Signature of Accountable Executive				



Copyright

Notification of Difference from IAGSA Recommended Practice					
Name of Company:	NRG Exploration CC/Skyhorse Aviation Pty Ltd				
Date submitted:	17/08/2023				
Which Recommended Practice or Safety Manual section is being deviated from?	Fuel Quality Control - Drums - Verify the expiry date of the drums.				
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)	
What is the reason for the deviation?	Alternate compliance procedure in place				
Has a risk assessment been completed for the deviation?	No				
Is an equivalent practice/standard in place?	Yes				
(If yes provide details)	Drums are examined on condition – printed expiry date on the drum not always available				
If No, what specific actions have been taken to provide for an equivalent level of safety?					
Name of Accountable Executive	Ryan Louw				
Signature of Accountable Executive					



Copyright

Notification of Difference from IAGSA Recommended Practice				
Name of Company:	NRG Exploration	NRG Exploration CC/Skyhorse Aviation Pty Ltd		
Date submitted:	17/08/2023			
Which Recommended Practice or Safety Manual section is being deviated from?	Monitoring of radios - During survey flights, are radios and transponders turned on and selected to the appropriate ATC or flight service frequencies.  Additionally, equipment permitting, common air to air and emergency frequencies (121.5MHz) should also be monitored.			
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)
What is the reason for the deviation?	Interference with magnetic data			
Has a risk assessment been completed for the deviation?	No			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)	Radios are on, however transponders are off during some survey flights if required.			
If No, what specific actions have been taken to provide for an equivalent level of safety?				
Name of Accountable Executive	Ryan Louw			_
Signature of Accountable Executive				



Copyright

Notification of Difference from IAGSA Recommended Practice				
Name of Company:	NRG Exploration	NRG Exploration CC/Skyhorse Aviation Pty Ltd		
Date submitted:	17/08/2023			
Which Recommended Practice or Safety Manual section is being deviated from?	length been dete	rmined by an aeron	Wing Aircraft - Has the nautical engineer as to mand tail rotors following the	inimize the
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)
What is the reason for the deviation?	Design by engine engineer	eers in towed array	and survey industry not	an aeronautical
Has a risk assessment been completed for the deviation?	No			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)		has been designed I tail rotor blades af	to mitigate the possibilit ter loss of load.	y of cable recoil
If No, what specific actions have been taken to provide for an equivalent level of safety?				
Name of Accountable Executive	Ryan Louw			
Signature of Accountable Executive				



Copyright

Notification of D	ifference fron	n IAGSA Recom	mended Practice	
Name of Company:	NRG Exploration CC/Skyhorse Aviation Pty Ltd			
Date submitted:	17/08/2023			
Which Recommended Practice or	Towed Geophysi	cal Arrays – Rotary	Wing Aircraft - Has the b	oreaking strain of
Safety Manual section is being deviated from?	the weak link bee	en specified by an a	eronautical engineer?	_
What is the duration of the deviation?	Permanent: X	Temporary: □	From: (mm/yy)To:	(mm/yy)
What is the reason for the deviation?				
Has a risk assessment been completed for the deviation?	No			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)	Breaking point ha	as been determined	l by a SANAS approved I	aboratory
If No, what specific actions have been taken to provide for an equivalent level of safety?				
Name of Accountable Executive	Ryan Louw			
Signature of Accountable Executive				



Copyright

Notification of Difference from IAGSA Recommended Practice				
Name of Company:	NRG Exploration CC/Skyhorse Aviation Pty Ltd			
Date submitted:	17/08/2023			
Which Recommended Practice or Safety Manual section is being deviated from?	Supplemental Safety Training Requirements - Is Survey Crew Resource Management training provided to all crew members assigned to survey operations including: geophysicists; pilots; equipment operators; maintenance engineers; field technicians and field support staff at intervals not exceeding three years?			
What is the duration of the deviation?	Permanent: □	Temporary: X	From: (08/23)To: (02/24)	
What is the reason for the deviation?	Survey Crew Resource training to be developed internally and implemented for all equipment operators; maintenance engineers; field technicians and field support staff by target date noted above			
Has a risk assessment been completed for the deviation?	No			
Is an equivalent practice/standard in place?	Yes			
(If yes provide details)	Pilots completing recurrent CRM annually, other crew members as per project requirements.			
If No, what specific actions have been taken to provide for an equivalent level of safety?				
Name of Accountable Executive	Ryan Louw			
Signature of Accountable Executive				